

JOYCE HALL ELEMENTARY SCHOOL (ES #15)

AS OF MAY 2022

WORK COMPLETED AND ONGOING:

Site

- Landscaping installation ongoing
- Sidewalk installation ongoing at the storm shelter
- Playground surfacing to begin shortly
- Canopy installation ongoing
- Exterior masonry installation ongoing at main entry tower

Building

- Exterior door installation at storm shelter
- Kitchen equipment deliveries and installation ongoing
- Floor tile installation ongoing at main corridor and cafetorium
- Millwork complete Areas 2 and& 3
- Installation of ceiling grid, lights, and diffusers ongoing – Areas 2 and 3
- Installation of plumbing fixtures and toilet accessories ongoing Areas 1, 2,3, and 4
- Tape, bed, and texture ongoing Areas 1 and 2










JOYCE HALL ELEMENTARY SCHOOL (ES #15)

AS OF MAY 2022









JOYCE HALL ELEMENTARY SCHOOL (ES #15)

AS OF MAY 2022










JOYCE HALL ELEMENTARY SCHOOL (ES #15)

AS OF MAY 2022










JOYCE HALL ELEMENTARY SCHOOL (ES #15)

AS OF MAY 2022










JOYCE HALL ELEMENTARY SCHOOL (ES #15)

AS OF MAY 2022









JOYCE HALL ELEMENTARY SCHOOL (ES #15)

AS OF MAY 2022









JOYCE HALL ELEMENTARY SCHOOL (ES #15)

AS OF MAY 2022









JOYCE HALL ELEMENTARY SCHOOL (ES #15)

AS OF MAY 2022











AS OF MAY 2022

WORK COMPLETED AND ONGOING:

Site

- Baseball field drainage and plastic field covering installation complete. Installing gravel now
- Softball field drainage has started
- Backfilling of Retaining Wall C complete
- Forming remainder of Retaining Walls G and F now
- Baseball and softball batting cage structures have been erected. Cages will be completed following completion of Area U (MPF)

Main Building

- Steel erection complete Areas A, B, C, Q, and R
- Steel erection ongoing Areas D and S
- MEP/Fire Sprinkler overhead installation ongoing Areas A, B, C, and Q
- Metal stud framing complete on first floor Areas A, B, and C
- Metal stud framing ongoing on second floor Area A
- Installation of CMU columns ongoing Area D

- Interior CMU walls ongoing Areas Q and R
- Roofing installation has started; Area A is dried in, and Area B is ongoing
- Window/Storefront installation has started; complete through Area A
- Exterior waterproofing complete Areas A, B, and East Courtyard; ongoing Area C
- Fireproofing complete on first floor and ongoing on second floor Areas A, B, and C

Multipurpose Facility (MPF) and Ancillary Buildings

- CMU wall installation ongoing Area T (MPF)
- Exterior masonry veneer ongoing Area V (MPF)
- Steel structure complete Area U (MPF); Roof strapping installation is ongoing
- CMU wall installation ongoing Pump House (Ancillary)







WALNUT GROVE HIGH SCHOOL (HS#3)

AS OF MAY 2022









WALNUT GROVE HIGH SCHOOL (HS#3)

AS OF MAY 2022









WALNUT GROVE HIGH SCHOOL (HS#3)

AS OF MAY 2022









WALNUT GROVE HIGH SCHOOL (HS#3)

AS OF MAY 2022

1











WALNUT GROVE HIGH SCHOOL (HS#3)

AS OF MAY 2022










WALNUT GROVE HIGH SCHOOL (HS#3)

AS OF MAY 2022











WALNUT GROVE HIGH SCHOOL (HS#3)

AS OF MAY 2022









WALNUT GROVE HIGH SCHOOL (HS#3)

AS OF MAY 2022









WALNUT GROVE HIGH SCHOOL (HS#3)

AS OF MAY 2022









WALNUT GROVE HIGH SCHOOL (HS#3)

AS OF MAY 2022





