

### **JOYCE HALL ELEMENTARY SCHOOL (ES #15)**

AS OF JUNE 2022


#### WORK COMPLETED AND ONGOING:

#### Site

- Landscape installation ongoing
- Playground surfacing on southeast playground ongoing
- Canopy installation ongoing
- Exterior masonry installation nearing completion at the entry tower

#### Building

- Kitchen equipment deliveries and installation ongoing
- Floor tile installation complete
- Millwork installed Areas 1 and 2
- Ceiling grid, lights and grills are being installed Areas 1 and 2
- Plumbing fixtures and accessories being installed Areas 1, 2, 3 and 4
- Tape, bed, and texture ongoing Area 1
- Door installation ongoing Areas 1, 2 and 3
- AV installation ongoing Areas 1, 2 and 3
- Fire alarm trim-out ongoing Areas 1 and 2
- Remaining Roof Top Units (RTU) installation to be complete by mid-month
- Punch has started Area 4
- Low Voltage engineer walks ongoing









### **JOYCE HALL ELEMENTARY SCHOOL (ES #15)**







### **JOYCE HALL ELEMENTARY SCHOOL (ES #15)**











### **JOYCE HALL ELEMENTARY SCHOOL (ES #15)**







### **JOYCE HALL ELEMENTARY SCHOOL (ES #15)**







### **JOYCE HALL ELEMENTARY SCHOOL (ES #15)**









### **JOYCE HALL ELEMENTARY SCHOOL (ES #15)**










### **JOYCE HALL ELEMENTARY SCHOOL (ES #15)**









### **JOYCE HALL ELEMENTARY SCHOOL (ES #15)**





### **WALNUT GROVE HIGH SCHOOL (HS#3)**

AS OF JUNE 2022

#### WORK COMPLETED AND ONGOING:

#### Site

- Baseball and softball fields are ready for turf, but it will not be installed for eight months
- Retaining Walls G and F are complete
- Detention pond flume installation ongoing
- Baseball and softball batting cages ongoing
- Sports lighting installation ongoing

#### Main Building

- Steel erection complete Areas A, B C, E, P, Q, R and S
- Steel erection is ongoing Areas D, N and M
- MEP/Fire Sprinkler overhead ongoing Areas A2, B2, C2, P and Q
- Framing complete (1st floor) Areas A, B, C and D
- Framing is ongoing (2nd floor) Area C
- CMU columns erection ongoing Area D
- Interior CMU wall erection ongoing Areas P, Q and R

- Roofing ongoing Areas A, B and C are dried-in; installation ongoing – Areas Q and R
- Window/Storefront installation ongoing; Complete through – Area C
- Exterior waterproofing ongoing Areas C and D
- Fireproofing ongoing Areas P and Q

#### Multipurpose Facility (MPF) and Ancillary Buildings

- Interior CMU wall erection ongoing Area T
- Exterior masonry ongoing Area V
- Steel structure is complete; roof strapping installation ongoing Area U
- CMU at pump house complete









### **WALNUT GROVE HIGH SCHOOL (HS#3)**









### **WALNUT GROVE HIGH SCHOOL (HS#3)**










### **WALNUT GROVE HIGH SCHOOL (HS#3)**










### **WALNUT GROVE HIGH SCHOOL (HS#3)**









### **WALNUT GROVE HIGH SCHOOL (HS#3)**







### **WALNUT GROVE HIGH SCHOOL (HS#3)**









### **WALNUT GROVE HIGH SCHOOL (HS#3)**









### **WALNUT GROVE HIGH SCHOOL (HS#3)**












### **WALNUT GROVE HIGH SCHOOL (HS#3)**









### **WALNUT GROVE HIGH SCHOOL (HS#3)**

