

BETTY JACKSON ELEMENTARY SCHOOL (ES #18)

AS OF OCTOBER 2023

WORK COMPLETED AND ONGOING:

Site

- Lime stabilization underneath paving ongoing
- Paving ongoing
- Underground utilities installation ongoing

Building

- Grade beam installation ongoing
- Slab prep and pour ongoing Area 4; Area 3 to follow









BETTY JACKSON ELEMENTARY SCHOOL (ES #18)









BETTY JACKSON ELEMENTARY SCHOOL (ES #18)









BETTY JACKSON ELEMENTARY SCHOOL (ES #18)










BETTY JACKSON ELEMENTARY SCHOOL (ES #18)









BETTY JACKSON ELEMENTARY SCHOOL (ES #18)










BETTY JACKSON ELEMENTARY SCHOOL (ES #18)





DANIEL L. JONES MIDDLE SCHOOL (MS #5)

AS OF OCTOBER 2023


WORK COMPLETED AND ONGOING:

Site

- Prestwick Road complete
- Sidewalk installation along Prestwick Road ongoing
- Coit Road turn lanes complete
- Football field subgrade prep ongoing
- Trench drain at football field 50% complete
- Pump house CMU complete
- All on-site paving is complete
- Flume installation in north detention pond ongoing
- Light pole installation is 98% complete
- Concession stand exterior CMU complete; exterior veneer ongoing
- Grading and topsoil installation ongoing

Building

- Exterior framing and sheathing ongoing Areas 1, 2, 3, 9, 10 and 11
- Fireproofing complete Areas 1, 2, 3, 9, 10 and 11
- MEP wall rough-in ongoing Areas 1, 2, and 3
- One siding sheetrock Areas 1, 2 and 3
- Window installation ongoing Areas 1, 2 and 3
- Steel erection ongoing Areas 4, 5 and 8
- Air-barrier installation ongoing Area 4
- CMU installation ongoing Areas 4, 5, 6 and 7
- Tornado shelter MEP rough-in ongoing
- Tornado shelter topping slab complete; roof installation ongoing
- Exterior veneer installation ongoing Areas 6 and 7
- Foamed-in-place insulation installation ongoing Areas 5, 6 and 7
- Fireproofing ongoing Area 7
- Roof installation ongoing Areas 7, 9, 10 and 11









DANIEL L. JONES MIDDLE SCHOOL (MS #5)









DANIEL L. JONES MIDDLE SCHOOL (MS #5)









DANIEL L. JONES MIDDLE SCHOOL (MS #5)









DANIEL L. JONES MIDDLE SCHOOL (MS #5)










DANIEL L. JONES MIDDLE SCHOOL (MS #5)










DANIEL L. JONES MIDDLE SCHOOL (MS #5)










DANIEL L. JONES MIDDLE SCHOOL (MS #5)










DANIEL L. JONES MIDDLE SCHOOL (MS #5)





W. H. MOSELEY MIDDLE SCHOOL (MS #6)

AS OF OCTOBER 2023

WORK COMPLETED AND ONGOING:

Site

- Underground utilities ongoing
- Site underground electrical ongoing
- Field construction ongoing
- Majority of site earthwork complete, except lime stabilization and final grading for paving

Building

- Grade beams ready to be poured Area 1
- MEP underground ongoing Areas 1 and 7
- Auger cast piles are 90% complete









W. H. MOSELEY MIDDLE SCHOOL (MS #6)









W. H. MOSELEY MIDDLE SCHOOL (MS #6)









W. H. MOSELEY MIDDLE SCHOOL (MS #6)










W. H. MOSELEY MIDDLE SCHOOL (MS #6)









RICHLAND HIGH SCHOOL (HS #4)

AS OF OCTOBER 2023

WORK COMPLETED AND ONGOING:

Site

- Final subgrade elevation checks on north parking lot complete
- Layout of North parking lot ongoing
- Paving pre-construction meeting complete
- First parking lot (north parking lot) pour complete
- Sanitary sewer line A and storm drain line C installation ongoing
- Installation of irrigation sleeves and underground electrical to light poles in South parking lots ongoing
- Liming of north fire lane and south parking lots ongoing

Building

- Auger cast piles complete Area A; ongoing Areas B, C and P
- Grade beam excavation and forming ongoing Area A
- First grade beam pour complete Area A











RICHLAND HIGH SCHOOL (HS #4)












RICHLAND HIGH SCHOOL (HS #4)










RICHLAND HIGH SCHOOL (HS #4)









RICHLAND HIGH SCHOOL (HS #4)









RICHLAND HIGH SCHOOL (HS #4)

